



GOOD



GAP HERE IS
CONTROLLED
BY BASE IDLE
SCREW ADJ.
"NORMAL"

WORN



BIG GAP

SHAFT
WEAR
ALLOWS
PLATE TO
SHIFT IN
BORE